

Surface Preparation



Scarifying




Shot Blasting



Planetary Grinding

CSP ①



Acid Etched

CSP ②




Grinding

CSP ③



Light Shotblast

CSP ④



Light Scarification

CSP ⑤



Medium Shotblast

CSP ⑥



Medium Scarification

CSP ⑦



Heavy Abrasive Blast

CSP ⑧



Scabbled

CSP ⑨



Heavy Scarification

APPLICATION

CSP

METHOD

Sealers
(0-3 mils)

CSP 1-3

Scrubbing, Low Pressure Water, Acid Etching, Sand Blasting, Shot Blasting

Thin-Film
(4-10 mils)

CSP 1-3

Scrubbing, Low Pressure Water, Acid Etching, Sand Blasting, Shot Blasting

High Build
(10-40 mils)

CSP 3-5

Grinding, Sand Blasting, Steel Shot Blasting, Scarifying, Needle Scaling

Self-Leveling
(50 mils - 1/8i)

CSP 4-6

Sand Blasting, Steel Shot Blasting, Scarifying, Needle Scaling, High/Ultra High Pressure Water Jetting

Polymer Overlay
(1/8i - 1/4i)

CSP 5-9

Sand Blasting, Steel Shot Blasting, Scarifying, Needle Scaling, High/Ultra High Pressure Water Jetting, Scabbling, Flame Blasting, Milling